

**Antler Energy LLC
Klaenhammer 1
Location ID: 312861**



Information missing



No sign at tank battery

Antler Energy LLC
Klaenhammer 1
Location ID: 312861



Debris



Damaged label

**Antler Energy LLC
Klaenhammer 1
Location ID: 312861**



Open end tank valve



Debris

Antler Energy LLC
Klaenhammer 1
Location ID: 312861



Debris



Debris

**Antler Energy LLC
Klaenhammer 1
Location ID: 312861**



Debris



Unregistered pit?

**Antler Energy LLC
Klaenhammer 1
Location ID: 312861**



Unused equipment



Required information missing

**Antler Energy LLC
Klaenhammer 1
Location ID: 312861**



Oily waste and stained soil



Debris

Antler Energy LLC
Klaenhammer 1
Location ID: 312861



Debris



Debris. Stained soil. No containment.

**Antler Energy LLC
Klaenhammer 1
Location ID: 312861**



Oily waste and staining



Oily waste and staining

**Antler Energy LLC
Klaenhammer 1
Location ID: 312861**



Open to wildlife



Location from North entrance

**Antler Energy LLC
Klaenhammer 1
Location ID: 312861**



Location from Southwest corner



Location from Southeast corner