

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/11/2025

Submitted Date:

03/11/2025

Document Number:

715501402

FIELD INSPECTION FORMLoc ID 313000 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10407

Name of Operator: ANTLER ENERGY LLC

Address: PO BOX 104

City: BAGGS State: WY Zip: 82321

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

18 Number of Comments

7 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hoak, Thomas	(720) 594-8372	thomas.hoak@state.co.us	Enforcement
Evans, Clay	(307) 380-7616	clay@antler-energy.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
100408	PIT	AC	01/01/1999		-	PTASYNski 1X TANK BATTERY	AC
223250	WELL	PR	09/22/1985	OW	081-06614	PTASYNski 1X	PR

General Comment:**ECMC Inspection Report Summary**

On Tuesday, 03/11/2025, Inspector Kirby Burchett, conducted a routine field inspection at Antler Energy LLC on the Ptasynski 1X well Location #313000, in Moffat County, Colorado.

This location is within or in close proximity to a Colorado Parks and Wildlife (CPW) District with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations the following compliance issue was observed:

1. Debris.
2. Stained soil.
3. Open end tank valve
4. No sign at tank battery.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No sign		
Corrective Action:	The Tank battery sign will be no less than 3 square feet and no more than 6 square feet, and will provide: Name of the Operator; Telephone number at which the Operator can be reached at all times; Telephone number for local emergency services (911 where available); The public road used to access the Tank battery site; Well name(s) and API number(s) associated with the Tank battery and the legal location of the Well(s); and Location, including the quarter/quarter section, of the Tank battery.	Date:	04/11/2025
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Required information missing		
Corrective Action:	The Wellhead sign will identify: The Well name; The API Number; and Its legal location, including the quarter/quarter section.	Date:	04/11/2025

Emergency Contact Number:

Comment: 307-380-7616

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	All excess materials, rubbish, supplies, trash, or other waste material will be properly contained until removed from the Oil and Gas Location. At no time will debris be placed or remain on the ground.	Date:	03/19/2025

Overall Good: ☐

Spills:			
Type	Area	Volume	
Crude Oil	WELLHEAD		
Comment:	Oily waste and staining		
Corrective Action:	Remove and properly dispose of oily waste, stained and/or contaminated soil.	Date:	03/27/2025
Crude Oil	Tank		
Comment:	Oily waste and impacted soil		
Corrective Action:	Remove and properly dispose of oily waste, stained and/or contaminated soil.	Date:	03/27/2025
Lube Oil	Pump Jack		
Comment:	Multiple areas under pumping unit and engine		
Corrective Action:	Remove and properly dispose of oily waste, stained and/or contaminated soil.	Date:	03/27/2025

In Containment: No

Comment: [Scrubber pots being drained on the ground.](#)
[Material Handling and Spill Prevention BMPs need implementation and maintenance.](#)

☒ Multiple Spills and Releases?

<u>Fencing/:</u>			
Type	PUMP JACK		
Comment:	Manufacturer		
Corrective Action:		Date:	
Type	PIT		
Comment:	Livestock wire		
Corrective Action:		Date:	

<u>Equipment:</u>			corrective date
Type: VRT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	400 BBLs	STEEL AST		,	
Comment:		Open end tank valve				
Corrective Action:		All load lines or tank valves that can be used as a load line will be capped or plugged.				Date: 03/17/2025

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:		Unlined		
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	400 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:		Date:				

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:		Unlined		
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:	Date:		

Flaring:

Type			
Comment:			
Corrective Action:	Date:		

Inspected Facilities									
Facility ID:	100408	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	AC
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	223250	Type:	WELL	API Number:	081-06614	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	December 2024 Production Reported								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action: Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID: <u>100408</u>	Lat:	Long:
Reference Point: <input type="text"/>	Other: <input type="text"/>	Length: <input type="text"/>	Width: <input type="text"/>	

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action: Date:

Fencing:

Fencing Type: Livestock Fencing Condition: Inadequate

Comment:

Corrective Action: Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action: Date:

Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard:

Comment: Pit appears washed out on East end

Corrective Action: Date:

Permit:	Facility ID	Permit Num	Expiration Date
	100408	403274103	<input type="text"/>
	100408	403274103	<input type="text"/>

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715501403	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6955022