

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/05/2025

Submitted Date:

03/05/2025

Document Number:

713601937

**FIELD INSPECTION FORM**

Loc ID 321153 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10560  
Name of Operator: WEST TEXAS OPERATING CO LLC DBA XTREME  
Address: PO BOX 2326  
City: VICTORIA State: TX Zip: 77902

**Findings:**

- 5 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
HAHN, MIKE		mhahn@xeogc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206161	WELL	PR	05/19/1998	GW	009-06577	REDSTONE 2-18	RI

**General Comment:**

This is a location inspection at the REDSTONE #2-18 wellsite.  
See attached photos and additional details within this report.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type WEEDS

Comment: There are weeds around the tank and equipment that need to be controlled.

Corrective Action: Comply with Rule 606.

Date: 03/12/2025

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Flow Line

#

corrective date

Comment: It does not appear that the flowlines have been registered.

Corrective Action: Submit an eForm 44 Flowline Report per Rule 1101.a.

Date: 04/05/2025

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		Open Top		

Comment: The netting on the open top tank is not maintained to prevent wildlife entry.

Corrective Action: Install or repair wildlife protection equipment.  
Comply with Rule 608.a.(13)

Date: 03/12/2025

**Paint**

Condition

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		Inadequate

Comment: There is insufficient secondary containment to prevent a spill. The berm is wore down and degraded.

Corrective Action: Repair or install berms or other secondary containment devices.

Date: 04/05/2025

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404116400	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6945610">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6945610</a>
713601938	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6945601">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6945601</a>