

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/03/2025

Submitted Date:

03/12/2025

Document Number:

698603232

FIELD INSPECTION FORM

Loc ID 337019 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Findings:

- 15 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281606	WELL	PR	11/28/2005	GW	125-09698	FRANSON 34-28 4N47W	PR

General Comment:

Routine Inspection.

On 3/3/2025 Inspector arrived at well location to complete routine well location inspection. Upon arrival Inspector discovered active release at wellhead. Fluid leak was at check valve on wellhead tree. Notified OWN Resources Field Formen via text message at 11:52 AM 3/3/2025. OWN Lease Operator responded to location prior to Inspector departure to address release. Spill estimated to be over one barrel.

Location			
Lease Road:			
Type	Access		
comment:	Active agricultural cropland with seasonal access to well location.		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign at wellhead location.		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Lease sign posted at remote Gas Meter Run.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Emergency contact information posted on Lease sign.		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
Produced Water	WELLHEAD	<= 1 bbl	
Comment:	Release at wellhead from check valve on wellhead tree water line. Standing fluid at wellhead with an approximately 15' X 20' wet/damp soil area.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: <u>03/04/2025</u>
In Containment: No			
Comment:	Reported to OWN Resources Operating LLC Field Foreman 3/3/2025 via text message at 11:52 AM. Lease Operator responded to location prior to Inspector departure.		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well location.		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:	Remote Gas Meter Run located on CR L & access at shared gathering location. Gas Meter Run. Chart in Meter Box dated 2-3-25. Meter Calibration/Test Log dated 2-12-24. Well Inlet Valve closed. Gas Outlet Valve open. **Meter due calibration**.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Pump Jack Power and Control Panel.		
Corrective Action:			Date:
Type: Pump Jack	# 1		

Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Shared Remote Gas Meter Shed. Roof is damaged.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric Motor.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing production. Rods and tubing in the wellbore. Tubing valve closed. **Open ended valve missing plug**. Casing valve open. Active release from wellhead tree check valve.		
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).	Date:	03/27/2025

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 281606 Type: WELL API Number: 125-09698 Status: PR Insp. Status: PR

Producing Well

Comment: Rods and tubing in wellbore. Tubing valve closed. Casing valve oped. Gas Meter Run Valves: Well inlet valve closed, Gas outlet valve open.
Electronic Well File reflects last Production/Status reported 1/1/2025 and Well Status as PR. Based on current valve settings at time of inspection the well is SI.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698603241	Leaking check valve video.	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6956051
698603242	Inspection photos.	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6956052