

Interim Reclamation and Stormwater Inspection

Date: 03/11/2025

Operator: BONANZA CREEK ENERGY OPERATING
COMPANY LLC - 8960

Location ID: 422253

Inspection Document #: 718700196

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Crow Valley 7-62-32-1M
Location ID: 422253



Photos 1 & 2. It appears that vehicle traffic is occurring in the interim areas with debris (hay/manure) observed in the northwest corner of the location.

Inspection Photos
Location Name: Crow Valley 7-62-32-1M
Location ID: 422253



Photos 3 & 4. Taken from the southeast (left; Photo 3) and northeast (right; Photo 4) corners of the location. The location does not appear to be progressing towards reclamation standards and regulations with little evidence of desirable native vegetation observed.

Inspection Photos
Location Name: Crow Valley 7-62-32-1M
Location ID: 422253



Photos 5 & 6. Taken from the northwest (left; Photo 5) and southwest (right; Photo 6) corners of the location. The location does not appear to be progressing towards reclamation standards and regulations with little evidence of desirable native vegetation observed.

Inspection Photos
Location Name: Crow Valley 7-62-32-1M
Location ID: 422253



Photo 7. Well API 123-33198 has a Form 6A (doc #403226263) with a plug and abandonment date of 12/31/2027.