

# Final Reclamation and Stormwater Inspection

Date: 03/11/2025

Operator: BONANZA CREEK ENERGY OPERATING  
COMPANY LLC - 8960

Location ID: 421455

Inspection Document #: 718700200

Weld County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Hoff 6-62 15-1H  
Location ID: 421455



**Photos 1 & 2.** Taken from the location entrance. Culvert, cattle guard and gate remain at the former entrance.

Inspection Photos  
Location Name: Hoff 6-62 15-1H  
Location ID: 421455



**Photos 3 & 4.** Taken from the start (Photo 3; left) and end, near location (Photo 4; right) of the access road. Evidence of road base material remains throughout.

Inspection Photos  
Location Name: Hoff 6-62 15-1H  
Location ID: 421455



**Photos 5 & 6.** Taken from the southeast (Photo 5; left) and southwest (Photo 6; right) of the location. The former location doesn't appear to be progressing towards reclamation standards as the area is predominantly bare/unstabilized soils, with little evidence of desirable vegetation observed.

Inspection Photos  
Location Name: Hoff 6-62 15-1H  
Location ID: 421455



**Photos 7 & 8.** Taken from the northwest (Photo 7; left) and northeast (Photo 8; right) of the location. The former location doesn't appear to be progressing towards reclamation standards as the area is predominantly bare/unstabilized soils, with little evidence of desirable vegetation observed.

Inspection Photos  
Location Name: Hoff 6-62 15-1H  
Location ID: 421455



**Photo 9.** Taken near the well location. The former location doesn't appear to be progressing towards reclamation standards as the area is predominantly bare/unstabilized soils, with little evidence of desirable vegetation observed.