

Interim Reclamation and Stormwater Inspection

Date: 03/11/2025

Operator: HIGHPOINT OPERATING CORPORATION -
10071

Location ID: 438766

Inspection Document #: 718700201

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Will 6-62-15_22 NENW
Location ID: 438766



Photos 1 & 2. Taken from the northeast corner (Photo 1; left) and northern portion of the interim areas (Photo 2; right). Appears the Operator has performed interim reclamation activities to reduce disturbance areas only needed for production operations, with the evidence vegetation establishment observed in the interim areas. A follow-up inspection will be performed during the active growing season to verify vegetative compliance.

Inspection Photos
Location Name: Will 6-62-15_22 NENW
Location ID: 438766



Photos 3 & 4. Taken from the northwest corner of the location (Photo 3; left), interim area pictured. Photo 4(right) illustrates example of trash/debris on the west side of the location.

Inspection Photos
Location Name: Will 6-62-15_22 NENW
Location ID: 438766





Photos 5 & 6. Hydrocarbon staining at loadout (Photo 5; left) and unused equipment on west side of tank battery (Photo 6; right).

Inspection Photos
Location Name: Will 6-62-15_22 NENW
Location ID: 438766



Photos 7 & 8. Taken from the southwest corner of the location. Appears the Operator has performed interim reclamation activities to reduce disturbance areas only needed for production operations, with the evidence vegetation establishment observed in the interim areas. A follow-up inspection will be performed during the active growing season to verify vegetative compliance. Also pictured, tumbleweed debris collecting along fence line.

Inspection Photos
Location Name: Will 6-62-15_22 NENW
Location ID: 438766




Photos 9 & 10. Examples of trash/debris observed on the southern portion of the location.

Inspection Photos
Location Name: Will 6-62-15_22 NENW
Location ID: 438766



Photos 11 & 12. Hydrocarbon staining observed near tank battery.

Inspection Photos
Location Name: Will 6-62-15_22 NENW
Location ID: 438766



Photos 13 & 14. Hydrocarbon staining observed at loadouts within tank battery.

Inspection Photos
Location Name: Will 6-62-15_22 NENW
Location ID: 438766



Photo 15. Hydrocarbon staining observed at wellhead.

Inspection Photos
Location Name: Will 6-62-15_22 NENW
Location ID: 438766



Photo 16. Taken from the southeast corner of the location. Appears the Operator has performed interim reclamation activities to reduce disturbance areas only needed for production operations, with the evidence vegetation establishment observed in the interim areas. A follow-up inspection will be performed during the active growing season to verify vegetative compliance.