



Sampling Photographic Log

Citation Arapahoe Unit 121 (23-32)



Fence down at location

Pipe laying on the ground.

Description:

1/28/2025 inspection

ECMC

See below for corrected
items



Fencing mentioned in the ECMC report has been stood up and secured.

Description:

Arapahoe Unit 121

Fencing secured.

Arapahoe Unit 121 (23-32)
3/5/2025



Pipes and risers previously
mentioned picked up.

Description:

Pipes mentioned in
previous inspections
picked up.