

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/13/2025

Submitted Date:

03/13/2025

Document Number:

697011136

FIELD INSPECTION FORM

Loc ID: 332648 Inspector Name: Peterson, Tom On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|---------|
| | | rbucogccinspectionreports@chevron.onmicrosoft.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 288923 | WELL | PR | 10/01/2024 | GW | 123-24675 | LLOYD 34-11 | PR |
| 289782 | WELL | PR | 10/01/2024 | GW | 123-24915 | LLOYD 31-14 | PR |

General Comment:

This is a routine audit. Any corrective actions from previous audits that have not been addressed are still applicable. There were no operator personnel on location at the time of this field audit.

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | x 2 | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|-----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Panel x 2 | | |
| Corrective Action: | | Date: | |

Equipment:

| Type | # | corrective date |
|--------------------|---|-----------------|
| Flow Line | # 2 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Plunger Lift | # 2 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Bradenhead | # 2 | |
| Comment: | Bradenhead valves are exposed at surface. | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|----------------------|----------|---------------------|---------|--------|
| | | | CENTRALIZED BATTERY | | |
| Comment: | Tank battery #481650 | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|------------------|----------------------|
| Condition | <input type="text"/> |
| Other (Content) | <input type="text"/> |
| Other (Capacity) | <input type="text"/> |
| Other (Type) | <input type="text"/> |

| Berms | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Venting: | | | | |
|--------------------|----|--|--|-------|
| Yes/No | NO | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Flaring: | | | | |
|--------------------|--|--|--|-------|
| Type | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Inspected Facilities

Facility ID: 288923 Type: WELL API Number: 123-24675 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 289782 Type: WELL API Number: 123-24915 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Seeding | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 697011137 | Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6958691 |