

**KT Resources LLC
Ant Hill Unit 21-22
Location ID: 398705**




Missing required information




Open to wildlife

KT Resources LLC
Ant Hill Unit 21-22
Location ID: 398705




Inadequate label



Leaking equipment. No gas calibration card displayed.

KT Resources LLC
Ant Hill Unit 21-22
Location ID: 398705



Inadequate label



Erosion

**KT Resources LLC
Ant Hill Unit 21-22
Location ID: 398705**



Erosion and sediment migration



Location from Southeast entrance

**KT Resources LLC
Ant Hill Unit 21-22
Location ID: 398705**



Location from Northeast corner



Location from Southwest corner