

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/03/2025

Submitted Date:

03/04/2025

Document Number:

715201835**FIELD INSPECTION FORM**Loc ID 321222 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 11060Name of Operator: PROWERS ENT LLCAddress: P O BOX 7City: LAMAR State: CO Zip: 81052**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Quint, Craig		craig.quint@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206342	WELL	AC	07/22/1979	DM	011-06089	BROYLES C-1	AC

General Comment:

SE Compliance Specialist Brian Welsh conducted an audit and routine field inspection of the well location and equipment

This is a DM well

Location

Lease Road:			
Type	Access		
comment:	Main gate is off of CR GG on the south side of the canal. Access wellhead on trail through the pasture passing by north side of old home going east to location		
Corrective ActionL		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign is hanging from the wellhead with minimal information		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	04/03/2025

Emergency Contact Number:

Comment:

Corrective Action: Date:

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	The stock tank is rusted and hasn't been used. Tank needs to be removed		
Corrective Action:	Comply with Rule 606	Date:	04/03/2025

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Wire fence around location is in disrepair		
Corrective Action:	Comply with Rule 606	Date:	04/03/2025

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:	Separator on north side of wellhead. Fire tube is removed		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Propane tank used as gas scrubber		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	206342	Type:	WELL	API Number:	011-06089	Status:	AC	Insp. Status:	AC
Producing Well									
Comment:	Well is used as a DM well. Valve seems to be closed at time of inspection but inoperable and unable to open. Tubing is 2 3/8" below production master valve								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Location is covered with vegetation

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404120247	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6950027
715201836	location photos of wellhead, fencing and equipment	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6950003