

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2025

Submitted Date:

03/07/2025

Document Number:

715201850

FIELD INSPECTION FORMLoc ID 485760 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10791

Name of Operator: WAVETECH HELIUM INC

Address: 1801 BROADWAY SUITE 600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Jobe, Patrick	(303) 534-3383	pjobe@wavetechenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
486424	WELL	DG	07/06/2024		017-07821	1 Wavetech Harker Family 31-22	WK

General Comment:

SE Compliance Specialist Brian Welsh conducted a workover inspection

Operator needs to comply with other CAs from inspection (713601921) on 2/26/25

Location

Lease Road:			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by frac tank		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease sign by county road		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Good Housekeeping:

Type	TRASH		
Comment:	Trash at the southwest corner of location needs removed		
Corrective Action:	Comply with Rule 606	Date:	04/06/2025
Type	STORAGE OF SUPL		
Comment:	Pallet with bucket and fittings is for the frac tank and allowed to be stored on location while workover operations are being conducted. Upon completion of the well, any unnecessary equipment will need to be removed		
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	500 BBLS	LVST		38.999730,-102.212060	
Comment:	Frac tank on location for swabbing process					
Corrective Action:						Date:

Paint

Condition	<input type="text"/>	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	

Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	486424	Type:	WELL	API Number:	017-07821	Status:	DG	Insp. Status:	WK
<div>Workover</div> <div><div>Comment:</div><div>RAM Swab Services on location to swab the well dry</div></div> <div><div>Corrective Action:</div><div></div><div>Date:</div><div></div></div>									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404120295	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6950123
715201874	swabbing unit and frac tank	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6950113
715201875	trash in the southwest corner	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6950114