

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/24/2025

Submitted Date:

03/07/2025

Document Number:

717100110**FIELD INSPECTION FORM**Loc ID 318791 Inspector Name: Rollins, Grace On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Anderson, Laurel		laurel.anderson@state.co.us	
Ahmadian, Alexander		alexander.ahmadian@state.co.us	
,		ECMCInspections@Oxy.com	All Inspections
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
Graber, Nikki		nikki.graber@state.co.us	
Macy Kiel		Macy_Kiel@oxy.com	Oxy Environmental

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
318791	LOCATION	AC			-	NRC TANK BATTERY 27N-4HZ	EI

General Comment:

ECMC Environmental Field Inspection Report Summary

Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. Contract electrical personnel were on location at the time of this field inspection. Photos attached to document site conditions.

Facility Name: NRC Tank Battery #27N-4HZ

Facility ID: 442143

Location ID: 318791

Date of Inspection: 02/24/2025

Spill is located immediately adjacent to:

-Crop fields

Current site status:

-Salt crusting is visible throughout the location.

-Salt crusting appears to be heaviest in the northwest corner of the facility.

-No stormwater BMPs were observed along the southern and eastern boundaries of the facility. Salt crusting is visible on a portion of the crop field immediately adjacent to the southern boundary of the facility.

-Stormwater BMPs and a stormwater drainage were observed along the northern boundary of the facility. Salt crusting is visible on the crop field adjacent to the northern boundary of the facility and follows the apparent stormwater drainage pathway originating at the pad.

Estimated extents of visible salt crusting: approximately 200 feet.

-A spill bucket at the production tank valve does not appear level; integrity is unknown.

See attached corrective actions.

Location					
Overall Good: <input type="checkbox"/>					
Emergency Contact Number:					
Comment:					
Corrective Action:				Date: _____	
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:				corrective date	
Type: Other	#				
Comment:		A spill bucket at the production tank valve does not appear level; integrity is unknown.			
Corrective Action:		Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 03/21/2025	
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Location Construction

Location ID: 442143 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:**Comment:** _____

Corrective Action: _____

Date: _____

Wildlife BMPs:**Comment:** _____

Corrective Action: _____

Date: _____

Comment: No stormwater BMPs were observed along the southern and eastern boundaries of the facility. Salt crusting is visible on a portion of the crop field immediately adjacent to the southern boundary of the facility.**Corrective Action:** Install or repair required BMPs per Rule 1002.f.(2)C.

Date: 03/21/2025

On Site Inspection (305):Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities									
Facility ID:	318791	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Salt crusting is visible throughout the location. Salt crusting appears to be heaviest in the northwest corner of the facility. No stormwater BMPs were observed along the southern and eastern boundaries of the facility. Salt crusting is visible on a portion of the crop field immediately adjacent to the southern boundary of the facility. Stormwater BMPs and a stormwater drainage were observed along the northern boundary of the facility. Salt crusting is visible on the crop field adjacent to the northern boundary of the facility and follows the apparent stormwater drainage pathway originating at the pad. Estimated extents of visible salt crusting: 200 feet.

Corrective Action: Operator shall immediately coordinate with the landowner and investigate the areas of salt crusting to determine if it is petroleum impacted soils. If it is a reportable spill/release; reporting shall follow Rule 912. If this is not a reportable release, Operator shall provide documentation in a FIRR.

Date: 04/06/2025

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____

Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404119970	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6949692
717100111	ECMC Photo Log - NRC Tank Battery #27N-4HZ	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6949676