

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/24/2025

Submitted Date:

03/07/2025

Document Number:

717100114**FIELD INSPECTION FORM**Loc ID 317973 Inspector Name: Rollins, Grace On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ahmadian, Alexander		alexander.ahmadian@state.co.us	
Monk, Ryan		ryan.monk@state.co.us	
Fritzler, Gene		gfritzler12@gmail.com	
Graber, Nikki		nikki.graber@state.co.us	
Anderson, Laurel		laurel.anderson@state.co.us	
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
485680	SPILL OR RELEASE	CL	12/19/2024		-	Production Tank	EI

General Comment:

ECMC Environmental Field Inspection Report Summary

Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 485680

Spill Name: Hopkins 41C-19-61N67W 19NENE

Remediation Project #: 37591

Facility ID: 317973

Reported Date of Discovery: 10/06/2023

Date of Inspection: 02/24/2025

Spill is located within or adjacent to:

-Dacono Municipality

-Crop Land

Current site status:

-An excavation remains open with weeds/debris covering portions of the floor.

-Orange construction fencing has fallen along the northern and eastern areas of the excavation. Fencing has not been installed around the western and southern portions of the excavation.

-Soil with gray staining was visible in the production tank and separator berms; no odor was observed.

-The production tank and separator berms did not appear to have been compacted. The production tank berm material was easily disturbed by probing with fingers using minimal force.

-NFPA placard is visible on the production tank. Production tank shares containment with an unlabeled tank.

-Pea gravel is visible on the base of the tank containment berm, and on the northern portion of the separator containment berm.

-A liner was observed beneath the pea gravel within the production tank berm.

-Tank valves are enclosed within clean plastic boxes.

-Metal panel fencing surrounds ancillary equipment.

-Signage with emergency contact number is visible.

See attached corrective actions.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	NFPA placard is visible on the production tank. Production tank shares containment with an unlabeled tank.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	05/06/2025

Emergency Contact Number:

Comment:	Signage with emergency contact number is visible.		
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds/debris cover portions of the excavation floor.		
Corrective Action:	Comply with Rule 606.	Date:	03/14/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Metal panel fencing surrounds ancillary equipment.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Orange construction fencing has fallen along the northern and eastern areas of the excavation. Fencing has not been installed around the western and southern portions of the excavation.		
Corrective Action:	Secure access to excavation in accordance with Rule 913.b.(5).B.i and ECMC Guidance 913.b.(5)B i-v.	Date:	03/21/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:						
Corrective Action:						Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth					
Comment:	The production tank and separator berms did not appear to have been compacted. The production tank berm material was easily disturbed by probing with fingers using minimal force.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date:	04/06/2025

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	485680	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: An excavation remains open with weeds/debris covering portions of the floor. Orange construction fencing has fallen along the northern and eastern areas of the excavation. Fencing has not been installed around the western and southern portions of the excavation. Soil with gray staining was visible in the production tank and separator berms; no odor was observed. Quarterly reporting is required under Remediation Project # 37591.

Corrective Action: Per the most recent submitted Form 27 (Doc. # 404032574) under Remediation Project # 37591: Additional sampling and remediation are required, impacts to soil remain in situ and undefined. Multiple COAs require resolution. Form 27 Doc. # 404032574, Operator shall begin remedial excavation to remove the confirmed impacts at HSW#4 by April 18, 2025. Operator shall notify ECMC Area EPS personnel no less than 72 hours prior to any sampling or backfill at this location. The next Form 27 is due on 03/19/2025.

Date: 04/18/2025

Reportable: _____

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404119972	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6949694
717100115	ECMC Photo Log - Hopkins 41C-19-61N67W 19NENE	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6949678