

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/13/2025

Submitted Date:

03/14/2025

Document Number:

717300253**FIELD INSPECTION FORM**Loc ID 329847 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250127	WELL	PA	02/26/2024	OW	123-17930	HSR-WILLIAM MAYER 5-22	PA

General Comment:ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected FacilitiesFacility ID: 250127 Type: WELL API Number: 123-17930 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Well is PA (HSR William Mayer 5-22); ECMC form 42 notice of start of plugging operations doc #403638420 received on 12/28/2023. Facility/ battery services additional wells. The off location flowline servicing 5-22 is AIP; no flowline riser at PA well. Flowline at HHS equipment is cut/ capped below grade and disconnected/ isolated (open excavation). Other flowline risers at HHS are OOSLAT (lock/ tags). No Oxy or contract personnel were on location at the time of field inspection.	maclarej	03/14/2025
As outlined on ECMC form 19 spill report Doc #404119900 received on 03/07/2025: While conducting flowline removal activities at the William Mayer 5-22A flowline, historically impacted soil was discovered beneath a directional change of the former flowline. The volume of the release is unknown. The flowline has been removed and will not be replaced.	maclarej	03/14/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300254	PA well and signage	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6960447
717300255	OLF AIP; open excavation at HHS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6960448