

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2025

Submitted Date:

03/09/2025

Document Number:

708905936

**FIELD INSPECTION FORM**Loc ID 334913 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

24 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
QB Energy		ecmc.inspections@qb-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211287	WELL	PR	08/01/2020	GW	045-07046	BJM 6-16	PR
264150	WELL	PR	03/06/2003	GW	045-08183	BJM 6-9C (P6)	PR
264151	WELL	PR	09/01/2018	GW	045-08184	COUEY 5-13B (P6)	PR
264528	WELL	PR	12/20/2002	GW	045-08920	BJM 6-16C (P6)	PR
264794	WELL	PR	04/14/2004	GW	045-08944	BJM 6-16D (P6)	PR

**General Comment:****CECMC Inspection/Audit Report Summary**

On 03/06/2025 at approximately 12:25 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection/audit at QB Energy BJM 6-16 (P6) Pad.

Location # 334913 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas.

While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

1. Stormwater - Lack of stabilization/compaction on location & tracking onto lease road/insufficient BMP's with a CA date of 03/24/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection/audit report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Signs at separators		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911/970-285-2615	
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				

**Equipment:**

			corrective date
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank Unable to locate FORM 4 SUNDRY for equipment/not in compliance with CECMC rules		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Powered SVE-AS trailer		
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	Pressure transducers located on bradenheads, bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
Comment:	Centralized containment Unlined containment				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:	Tanks not equipped with telemetry				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
Comment:	Centralized containment Unlined containment				
Corrective Action:				Date:	
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities				
Facility ID:	211287	Type:	WELL	API Number: 045-07046 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	264150	Type:	WELL	API Number: 045-08183 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	264151	Type:	WELL	API Number: 045-08184 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	264528	Type:	WELL	API Number: 045-08920 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	264794	Type:	WELL	API Number: 045-08944 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Fail					Gravel insufficient
		Gravel				Sparse to none in most sections
		Culverts				
				Vehicle Tracking	Fail	Tracking onto lease road
Compaction	Fail					Lack of stabilization/compaction/insufficient BMPs
		Compaction				Light compaction in some sections
		Ditches				

Comment: [1. Lack of stabilization/compaction on location & tracking onto lease road/insufficient BMP's](#)Corrective Action: [Comply with CECMC Stormwater rules](#)

Date: 03/24/2025

**Pits:** ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<a href="#">Please refer to Stormwater for corrective action</a>	smelserw	03/09/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404120594	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6951377">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6951377</a>
708905937	Inspection/Audit 708905936 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6951371">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6951371</a>
708905938	Inspection/Audit 708905936 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6951372">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6951372</a>