

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/05/2025

Submitted Date:

03/10/2025

Document Number:

708303548

FIELD INSPECTION FORM

Loc ID: 334887 Inspector Name: Morris, Matthew On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Popejoy, Dusty		dusty.popejoy@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456935	Domestic Tap	AC	08/28/2018		-	Domestic Tap GM 44-2	AC

General Comment:

[CECMC Audit Report Summary](#)

On 3/5/2025 at approximately 11:05, Compliance Inspector Matthew Morris conducted a domestic tap audit at TEP ROCKY MOUNTAIN LLC, Domestic Tap/GM44-2 at Facility ID #456935 in Garfield County, Colorado.

During the audit, the following compliance issues were observed:

- 1) PRV on knock out terminates in an unsafe manner

A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
	Comment: Wellhead sign is weathering but legible.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911/(970)285-9377		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
	Comment: Hog panels		
Corrective Action:		Date:	

Equipment:

					corrective date
Type: Other	# 1				
Comment:	Domestic tap				
Corrective Action:		Date:			
Type: Other	#				
Comment:	PRVs on knock out terminate in an unsafe manner.				
Corrective Action:	Comply with CECMC pressure safety rules.	Date:			03/18/2025

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 456935 Type: Domestic Tap API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404122098	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6953271
708303549	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6953261