

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/06/2025

Submitted Date:

03/10/2025

Document Number:

710100352

FIELD INSPECTION FORM

Loc ID 420232 Inspector Name: Anderson, Laurel On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Noble, Legacy		rbucogccinspectionreports@chevron.onmicrosoft.com	All Legacy Noble Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420232	LOCATION	AC			-	MOSER H27-79HN	EI

General Comment:

ECMC Environmental Inspection of the following Chevron (Operator) facilities:
[Moser PC H22-33 Tank Battery Facility ID 489488/Location ID 420232](#)

Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no Operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Current site status:

- Peeling paint and signage/labels
- Missing tank content labels (Northernmost AST)
- Loadout piping missing camlock
- Weeds/debris/trash
- Standing water around concrete partially buried produced water vaults
- Tank contents/volume labels too small

Location

Overall Good:

Signs/Marker:

	Type	TANK LABELS/PLACARDS
	Comment:	Tank content and volume labels missing/too small to read at a distance and peeling. NFPA placards peeling.
	Corrective Action:	Install sign to comply with Rule 605.h.
		Date: 05/09/2025

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>	
Corrective Action:	<input style="width: 95%;" type="text"/>	Date: _____

Good Housekeeping:

Type	OTHER	
	Comment:	Lack of maintenance/good housekeeping procedures. Weeds/trash/debris observed on location at the time of inspection (see photos).
	Corrective Action:	Comply with Rules 606 and 1002.f.(2).D.
		Date: 03/17/2025

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

	Type: Ancillary equipment	#		corrective date
	Comment:	Loadout connection unsecured (no cap/lock on camlock coupling) - See photos.		
	Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		,
	Comment:	Fiberglass 300 bbl AST (north end) no content label. Appears to be painted; paint is peeling.			
	Corrective Action:				Date:

Paint

Condition	<input style="width: 95%;" type="text"/>
Other (Content)	<input style="width: 95%;" type="text"/>
Other (Capacity)	<input style="width: 95%;" type="text"/>
Other (Type)	<input style="width: 95%;" type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
	Comment:	<input style="width: 95%;" type="text"/>		
	Corrective Action:			Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	<100 BBLs	CONCRETE SUMP/VAULT		,
Comment: Two 60 bbl partially buried concrete produced water vaults. Water has pooled around both vaults.					
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					Date:
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	300 BBLs	STEEL AST		,
Comment: Paint peeling					
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Insufficient			
Comment:					Date:
Corrective Action:					Date:
Venting:					
Yes/No					
Comment:					Date:
Corrective Action:					Date:
Flaring:					
Type					
Comment:					Date:
Corrective Action:					Date:

Inspected Facilities

Facility ID: 420232 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404121782	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6952830
710100353	2025_0306_ Moser PC H22-33 Photo Documentation	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6952823