

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/06/2025

Submitted Date:

03/10/2025

Document Number:

710100354

**FIELD INSPECTION FORM**

Loc ID 421031 Inspector Name: Anderson, Laurel On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Noble, Legacy		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Legacy Noble Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421031	LOCATION	AC			-	DECHANT 3-19HZ	EI

**General Comment:**

ECMC Environmental Inspection of the following Chevron (Operator) facilities:  
Dechant 3,4-19HZ Tank Battery  
Facility ID 489489/Location ID 421031

Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no Operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Current site status:  
-ASTs rusted/peeling paint  
-Minor weeds/trash/debris

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type OTHER

Comment: Lack of maintenance/good housekeeping procedures. Minor weeds/trash/debris observed on location at the time of inspection (see photos).

Corrective Action: Comply with Rules 606 and 1002.f.(2).D.

Date: 03/17/2025

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL			STEEL AST		

Comment: Tanks are rusted/have peeling paint.

Corrective Action: Inspect, maintain and repair tanks to comply with Rule 609.b.

Date: 04/09/2025

**Paint**

Condition Inadequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 421031 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404121783	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6952835">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6952835</a>
710100355	2025_0306_ Dechant 3,4-19HZ_Photo Documentation	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6952824">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6952824</a>