

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2025

Submitted Date:

03/10/2025

Document Number:

710100356

**FIELD INSPECTION FORM**Loc ID 429363 Inspector Name: Anderson, Laurel On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
Kiel, Macy		Macy_Kiel@oxy.com	Staff Environmental Engineer
,		ECMCInspections@Oxy.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442606	TANK BATTERY	AC	07/23/2015		-	CANNON TANK BATTERY 16N-E3HZ	EI

**General Comment:**

ECMC environmental inspection to determine progress on the Cannon 36N-W3HZ Separator spill (Spill ID 489259). Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Cannon 36N-W3HZ Facility  
Spill ID 489259  
Tank Battery Facility ID 442606

**Incident information:**

Spill Discovery Date: 2/7/2025  
Days since spill discovery: 31 days (as of 3/10/2025)  
Last report: 19s 02/14/2025

Current site status: Separator has been disconnected and set aside to allow for remedial excavation, separator has oil and oil stained soil falling off onto ground surface below, hydrocarbon staining and odor present within the open excavation, soil appears to be comprised of silty sand/sandy silt. Water in the base of the excavation appears to be from hydrovacuuming to expose the flowlines/piping beneath the separator, orange construction fencing has fallen, gate to tank battery was open and unsecured upon arrival.

Inspected Facilities									
Facility ID:	442606	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: Separator has been disconnected and set aside to allow for remedial excavation, separator has oil and oil stained soil falling off onto ground surface below, hydrocarbon staining and odor present within the open excavation, soil appears to be comprised of silty sand/sandy silt.

Corrective Action: Pursuant to Rule 912.b.(6) Operator is required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure pursuant to Rule 913.h and supported by adequate documentation to demonstrate that the Spill or Release has been fully cleaned up and complies with Table 915-1; or A Form 27 if any of the criteria listed in Rules 912.b.(6).B.i-iii apply. If Remediation will continue under an approved Form 27, the Operator will also submit a Form 19 – Supplemental which requests closure of the Spill or Release and includes the Remediation project number assigned by the Director. Closure of this spill is due by January 6th, 2023.

Date: 05/08/2025

Reportable: YES

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404122002	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6953065">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6953065</a>
710100357	2025_0306_ Cannon 36N-W3HZ Separator Spill_Photo Documentation	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6953062">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6953062</a>