

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2025

Submitted Date:

03/10/2025

Document Number:

710100358**FIELD INSPECTION FORM**Loc ID 409754 Inspector Name: Anderson, Laurel On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mickelson, Erik		Erik_Mickelson@oxy.com	<a href="#">Oxy Environmental</a>
,		ECMCInspections@Oxy.com	<a href="#">All Inspections</a>
Kiel, Macy	970-515-1110	Macy_Kiel@oxy.com	<a href="#">Staff Environmental Engineer</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
409754	LOCATION	AC			-	WHITESIDE-62N65W 2NWSW	EI
412085	WELL	SI	12/01/2023	GW	123-30379	PIONEER 14-2	SI
412086	WELL	PA	12/13/2021	OW	123-30380	PIONEER 12-2	PA
412087	WELL	SI	11/01/2020	OW	123-30381	PIONEER 19-2	SI
412088	WELL	PA	12/14/2021	OW	123-30382	PIONEER 33-2	PA
412090	WELL	SI	10/01/2021	OW	123-30383	PIONEER 23-2	SI
412091	WELL	SI	10/01/2021	OW	123-30384	PIONEER 35-2	SI

**General Comment:**

ECMC Environmental Inspection of the following Kerr McGee/Oxy (Operator) facilities:

[WHITESIDE-62N65W Tank Battery](#)[Location ID 409754](#)[123-30379 PIONEER 14-2 Well](#)[123-30380 PIONEER 12-2 Well](#)[123-30381 PIONEER 19-2 Well](#)[123-30382 PIONEER 33-2 Well](#)[123-30383 PIONEER 23-2 Well](#)[123-30384 PIONEER 35-2 Well](#)

Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no Operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

[Note: Photos are labelled Pioneer 14, 19,35-2 based on wellhead signage present on location.](#)

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Signage down at northernmost wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds present throughout the location and wellheads.		
Corrective Action:	Comply with Rules 606.c. and 1003.f.	Date:	03/17/2025

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 409754	Type: LOCATION	API Number: -	Status: AC	Insp. Status: EI
---------------------	----------------	---------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 412085	Type: WELL	API Number: 123-30379	Status: SI	Insp. Status: SI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 412086	Type: WELL	API Number: 123-30380	Status: PA	Insp. Status: PA
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 412087	Type: WELL	API Number: 123-30381	Status: SI	Insp. Status: SI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 412088	Type: WELL	API Number: 123-30382	Status: PA	Insp. Status: PA
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 412090	Type: WELL	API Number: 123-30383	Status: SI	Insp. Status: SI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 412091	Type: WELL	API Number: 123-30384	Status: SI	Insp. Status: SI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404122003	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6953070">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6953070</a>
710100359	WHITESIDE-62N65W Location Photo Documentation	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6953063">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6953063</a>