

Inspection/Audit Photos
Location Name: QB Energy BENZEL 36-3A1 (B36) Pad
Location #: 335228



Photo # 3017 From entrance to location



Photo # 3018 Location



Inspection/Audit Photos
Location Name: QB Energy BENZEL 36-3A1 (B36) Pad
Location #: 335228



Photo # 3019 Location



Photo # 3020 Location

Inspection/Audit Photos
Location Name: QB Energy BENZEL 36-3A1 (B36) Pad
Location #: 335228



Photo # 3021 Location



Photo # 3022 Location

Inspection/Audit Photos
Location Name: QB Energy BENZEL 36-3A1 (B36) Pad
Location #: 335228



Photo # 3023 Location



Photo # 3024 Location

Inspection/Audit Photos
Location Name: QB Energy BENZEL 36-3A1 (B36) Pad
Location #: 335228



Photo # 3025 Secondary containment insufficient/does not comply with CECMC rules



Photo # 3026 Secondary containment insufficient/does not comply with CECMC rules

Inspection/Audit Photos
Location Name: QB Energy BENZEL 36-3A1 (B36) Pad
Location #: 335228



Photo # 3027 Secondary containment insufficient/does not comply with CECMC rules



Photo # 3028 Secondary containment insufficient/does not comply with CECMC rules

Inspection/Audit Photos
Location Name: QB Energy BENZEL 36-3A1 (B36) Pad
Location #: 335228



Photo # 3029 Tank labels damaged & additionally tank capacity is incorrect




Photo # 3030 Tank capacity