

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/28/2025

Submitted Date:

03/11/2025

Document Number:

698603198

FIELD INSPECTION FORM

Loc ID 337119 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10536
Name of Operator: SMITH ENERGY LLC
Address: 1540 MAIN ST SUITE 218 #334
City: WINDSOR State: CO Zip: 80550

Findings:

- 20 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Smith, Chris	970-330-7034	smithenergy@live.com	
Pesicka, Conor		conor.pesicka@state.co.us	
Smith, Glenn	970-330-7034	gsmithten@what-wire.com	
Waggoner, Kyle		kyle.waggoner@state.co.us	Eastern Environmental Supervisor

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282659	WELL	PR	04/01/2017	GW	125-09822	PAULI 3-7	PR

General Comment:

Routine Inspection.

Location			
Lease Road:			
Type	Access		
comment:	Active agricultural cropland with seasonal access to well location.		
Corrective Action		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Content/Quantity/Hazard sign at produced water tank. Sign has faded and is unreadable. Stickers over previous operator information are peeling and require replacement.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	04/11/2025
Type	BATTERY		
Comment:	Lease sign posted at remote Gas Meter Run. Stickers over previous operator information are peeling and require replacement.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign at wellhead location. Stickers over previous operator information are peeling and require replacement.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Emergency contact information posted on Lease sign.		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well location.		
Corrective Action:		Date:	
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:	Bradenhead plumbed to surface. **Open ended valve missing plug**.		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Inlet valve closed.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Rods removed and tubing in the wellbore. Tubing valve open. Casing valve closed.		

Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Remote Separator Shed.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Remote Gas Meter Shed.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Remote Gas Meter Run located on CR 53 & CR Q at shared gathering location. Gas Meter Run. Chart in Meter Box dated 2-27-25. Meter Calibration/Test Log dated 9-15-23. Well Inlet Valve closed. Gas Outlet Valve open. Meter not calibrated annually.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date: 04/11/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PLASTIC AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	24 BBL
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Earth berms are weather worn.			
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 282659 Type: WELL API Number: 125-09822 Status: PR Insp. Status: PR

Producing Well

Comment: Tubing valve open. Casing valve closed. Gas Meter Run Valves: Well inlet valve closed, Gas outlet valve open.

Electronic Well File reflects last Production/Status reported 12/1/2024 and Well Status as PR. Based on current valve settings at time of inspection the well is SI.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: _____ Lat: _____ Long: _____

Reference Point: _____ Other: _____ Length: 15 Width: 15

Lining:

Liner Type: _____ Liner Condition: _____

Comment: None. Pit appears to be produced water overflow pit for tank at gathering location located on CR 53 & CR Q. No fluids in pit at time of inspection. Review of COGIS electronic well file does not reflect pit has been registered or permitted.

Corrective Action Submit an eForm 15 Pit Report to update COGCC records with current information to comply with rule 909.

Date: 03/27/2025

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: None.

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: None

Corrective Action

Date: _____

Anchor Trench Present: NO Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404122345	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6953726
698603215	Inspection photos.	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6953725