

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2025

Submitted Date:

03/11/2025

Document Number:

698603209**FIELD INSPECTION FORM**Loc ID 303554 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253281	WELL	PR	12/30/1999	GW	125-07158	W. KORF 3	PR

General Comment:

Routine Inspection.

Location				
Lease Road:				
Type	Access			
comment:	Two track off maintained County Road.			
Corrective Action				Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Lease sign at wellhead location. Stickers over previous operator information are peeling and require replacement.			
Corrective Action:				Date:
Type	BATTERY			
Comment:	Lease sign posted at remote Gas Meter Run. Stickers over previous operator information are peeling and require replacement.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Content/Quantity/Hazard sign at produced water tank is faded and unreadable.			
Corrective Action:	Install sign to comply with Rule 605.h.			Date: 04/11/2025
Emergency Contact Number:				
Comment:	Emergency contact information posted on Lease sign.			
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Gas Meter Run	# 1			corrective date
Comment:	Remote Gas Meter Run located on CR & Access. Gas Meter Run. Chart in Meter Box dated 2-3-25. Meter Calibration/Test Log dated 10-14-24. Well Inlet Valve open. Gas Outlet Valve open.			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	Bradenhead plumbed to surface.			
Corrective Action:				Date:
Type: Flow Line	# 1			
Comment:	Flowline riser at vertical separator open ended.			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Wellhead. Rods removed from well. Tubing in the wellbore. Tubing valve open. Casing valve open.			

Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Remote Separator/Gas Meter Shed. Roof damaged.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	OTHER		,	
Comment:	Buried tank made of unknown material located at gathering location.					
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)	30 BBL	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	None.				
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	253281	Type:	WELL	API Number:	125-07158	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Tubing valve open. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open. Electronic Well File reflects last Production/Status reported 1/1/2025 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.								
Corrective Action:								Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404123592	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6954849
698603225	Inspection photos.	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6954848