

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/17/2025

Submitted Date:

03/18/2025

Document Number:

708700095

**FIELD INSPECTION FORM**

Loc ID 326334 Inspector Name: Kosola, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Findings:**

2 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, SIMCOE		sjninspections@ikavenergy.co	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216249	WELL	PR	12/31/2001	CBM	067-07855	FOREST POFF A 1	EI

**General Comment:**

[This is an environmental inspection only. All ongoing/unaddressed corrective actions from previous inspections remain applicable.](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		
Other	WELLHEAD			
Comment: <span style="color: blue;">Stained soil around wellhead. Non reportable spill volume.</span>				
Corrective Action: <span style="color: red;">Control and contain spills/releases and clean up per Rule 912.a.</span>			Date: <u>04/19/2025</u>	

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

**Flaring:**

Type	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

**Inspected Facilities**

Facility ID: 216249 Type: WELL API Number: 067-07855 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708700096	Inspection photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6965017">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6965017</a>