

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404132988

Date Received:
03/18/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10407

Name of Operator: ANTLER ENERGY LLC

Address: PO BOX 104

City: BAGGS State: WY Zip: 82321

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Evans, Clay	(307) 380-7616	clay@antler-energy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 715500873

Inspection Date: 11/01/2024 FIR Submit Date: 11/02/2024 FIR Status: _____

Inspected Operator Information:

Company Name: ANTLER ENERGY LLC Company Number: 10407

Address: PO BOX 104

City: BAGGS State: WY Zip: 82321

LOCATION - Location ID: 312941

Location Name: SHELL CREEK FEDERAL 44-27-612N99W Number: 27SESE County: MOFFAT

Qtrqr: SESE Sec: 27 Twp: 12N Range: 99W Meridian: 6

Latitude: 40.965390 Longitude: -108.499950

FACILITY - API Number: 05-081-00 Facility ID: 222951

Facility Name: SHELL CREEK FEDERAL 44-27 Number: 4

Qtrqr: SESE Sec: 27 Twp: 12N Range: 99W Meridian: 6

Latitude: 40.965390 Longitude: -108.499950

CORRECTIVE ACTIONS:

1 CA# 200224

Corrective Action: The Wellhead sign will identify: The Well name; The API Number; and Its legal location, including the quarter/quarter section. Date: 12/02/2024

Response: CA COMPLETED Date of Completion: 01/15/2025

Operator Comment: The well head sign has all of the required info.

ECMC Decision: _____

ECMC Representative:

2 CA# 200225

Corrective Action: The Tank battery sign will be no less than 3 square feet and no more than 6 square feet, and will provide: Name of the Operator; Telephone number at which the Operator can be reached at all times; Telephone number for local emergency services (911 where available); The public road used to access the Tank battery site; Well name(s) and API number(s) associated with the Tank battery and the legal location of the Well (s); and Location, including the quarter/quarter section, of the Tank battery.

Date: 12/02/2024

Response: CA COMPLETED

Date of Completion: 01/15/2025

Operator Comment:

Tank Battery sign installed

ECMC Decision: _____

ECMC Representative:

3 CA# 200226

Corrective Action: Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.

Date: 11/12/2024

Response: CA COMPLETED

Date of Completion: 01/15/2025

Operator Comment:

New tank lables installed

ECMC Decision: _____

ECMC Representative:

4 CA# 200227

Corrective Action: Repair or replace valve.

Date: 12/02/2024

Response: CA COMPLETED

Date of Completion: 01/15/2025

Operator Comment:

The Surface casing valve has been verified open. An operator of Antler Energy can be present to show the ECMC inspector that it is open to verify that there is no pressure on the surface casing.

ECMC Decision: _____

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Clay Evans

Signed: _____

Title: President

Date: 3/18/2025 6:26:08 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404132988	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files