

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/18/2025

Submitted Date:

03/18/2025

Document Number:

714202277

**FIELD INSPECTION FORM**Loc ID 326735 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		cogcc@kpk.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245784	WELL	SI	05/01/2021	GW	123-13579	SERAFINI 'B' 3	SI

**General Comment:**

This is an inspection in response to complaint DOC#: 404128022

Inspected Facilities									
Facility ID:	245784	Type:	WELL	API Number:	123-13579	Status:	SI	Insp. Status:	SI
Complaint									
Comment:	<p>Inspection in response to complaint. Field Inspector Assigned: Brittani Santistevan Complaint Received Date: 03/14/2025 Complaint Contacted: No Date: N/A Time: N/A Location ID #: 326735 Location Name: SERAFINI B #3 Inspection Document #: 714202271 Complaint inspection document #: 714202277 Complaint Document Form 18 #: 404128022 Nature of Complaint: Air quality/odor Field Inspector Actions: On 03/18/2025, I, Brittani Santistevan, area field inspector was assigned a complaint received by ECMC staff in reference to the nature of the complaint listed above. I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I did identify these complaints coming from the location(s) documented above. The facility was shut-in at the time of inspection. Although it is not captured in the attached FLIR video, there is a "bubble test" (soapy water sprayed onto the equipment) that was preformed indicating the pumpjack was omitting some type of emissions. Weather conditions: sunny, dry ground. A violation of ECMC rules was observed at the time of the inspection. All information has been reviewed and site inspection information has been submitted to the ECMC for further review.</p>								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									