

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/11/2025

Submitted Date:

03/12/2025

Document Number:

709100492

FIELD INSPECTION FORM

Loc ID 312320	Inspector Name: Heibel, Krystal	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 15 Number of Comments 11 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: ECMC Operator Number: 17180 Name of Operator: CITATION OIL & GAS CORP Address: 14077 CUTTEN RD City: HOUSTON State: TX Zip: 77069				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Krystal Heibel		krystal.heibel@state.co.us	
Harris, Debra		dharris@cogc.com	
Kyle Waggoner		kyle.waggoner@state.co.us	
Rogers, Bob	(719)767-3415/ (719) 431-0236	brogers@cogc.com	All Inspections
WARD, SHARON	281-891-1556	sward@cogc.com	Principal Agent
Kennedy, Herschel	(719) 767-3401/ (719) 671-3787	hkennedy@cogc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275837	WELL	PR	07/01/2022	OW	075-09340	SINDT 13	EI
312320	LOCATION	AC			-	SINDT-610N52W 31SESW	EI

General Comment:

On March 11, 2025, ECMC Environmental Unit Staff Krystal Heibel inspected the SINDT-610N52W 31SESW location (Location ID: 312320), the Sindt 13 wellhead (API 05-075-09340) and pit on location.

This is a follow-up inspection, from the previous Environmental inspection conducted on May 23, 2024 (Inspection Doc#709100292).

The work site is in close proximity to Beall Creek.

Any corrective actions from previous forms that have not been addressed are still applicable. Photos are attached to document site conditions at the time of the inspection.

LocationOverall Good: ☐

Signs/Marker:			
Type			
Comment:	No NFPA placard on poly tank. See photo 22.		
Corrective Action:	Install sign to comply with CDPHE rules.		Date: 04/11/2025
Type	TANK LABELS/PLACARDS		
Comment:	Emergency contact number illegible from a distance from tanks		
Corrective Action:	Emergency contact number illegible from a distance from tanks Install sign to comply with Rule 605.h.		Date: 07/04/2024

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	TRASH		
Comment:	Trash observed throughout location.		
Corrective Action:	Comply with Rule 606.		Date: 09/04/2024
Type	OTHER		
Comment:	E&P Waste (buckets of crude oil located within metal shed) not properly stored, handled, transported, treated, or disposed per Rule 905		
Corrective Action:	Handle waste in accordance with Rule 905 and conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).D.		Date: 09/04/2024
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment (metal fence, piping, black secondary containment trays, chemical barrels, metal stepover, bucket, wire) observed on location. See photo documentation.		
Corrective Action:	Comply with Rule 606		Date: 09/04/2024
Type	OTHER		
Comment:	Wildlife protections devices (netting) not adequate on secondary containment of black plastic bins. See photo documentation.		
Corrective Action:	Install or repair wildlife protection equipment.		Date: 09/04/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	
Crude Oil			
Comment:	Stained soil located throughout site, including outside the tank's secondary containment, within metal shed next to pump, outside of metal shed, next to wellheads. See photo documentation.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. In accordance with 913.d. (1) Operator will investigate impacts to soil, groundwater, and surface water as soon as the impacts are discovered. Additionally, Operator shall provide an explanation of how the volume of liquids spilled was calculated on a Form 19 Supplemental Report and comply with Rule 912 series rules for Spills and Releases.		Date: 06/06/2024
	Tank		
Comment:	Hydrocarbons spill/release observed from top and sides of tanks (next to metal shed connection). See photo documentation.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: 07/04/2024

Comment:	At the time of this inspection, Staff observed a hydrocarbon release/spill within the metal shed. Staff was unable to determine the approximate volume. After review, Environmental Staff have determined that the spill/release is reportable per Rule 912.b. Refer to attached inspection photos for documentation.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. In accordance with 913.d. (1) Operator will investigate impacts to soil, groundwater, and surface water as soon as the impacts are discovered. Additionally, Operator shall provide an explanation of how the volume of liquids spilled was calculated on a Form 19 Supplemental Report and comply with Rule 912 series rules for Spills and Releases.		Date:	06/06/2024
	WELLHEAD			
Comment:	Lube oil observed at the polish rod of wellhead (API 075-09340)			
Corrective Action:	Inspect, maintain and repair tanks to comply with rule 609.b. Immediately remove oily waste.		Date:	07/04/2024

In Containment: No

Comment: Hydrocarbons observed within lined pit containment.

☒ Multiple Spills and Releases?

Equipment:			corrective date
Type:	#		
Comment:	Pit on location is unregistered with the current operator.		
Corrective Action:	Submit an eForm 15 Pit Report to update ECMC records with current information to comply with rule 908.		Date: 09/14/2024

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 275837	Type: WELL	API Number: 075-09340	Status: PR	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 312320	Type: LOCATION	API Number: -	Status: AC	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404124986	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6956189
709100493	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6956180