

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage RWF 23-25 Frac

Location ID: 433757



Photo # 4647 From entrance to location




Photo # 4648 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage RWF 23-25 Frac

Location ID: 433757



Photo # 4649 Location



Photo # 4650 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage RWF 23-25 Frac

Location ID: 433757



Photo # 4651 Interior of pump house



Photo # 4652 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage RWF 23-25 Frac

Location ID: 433757



Mar 17, 2025 at 12:55:27 PM
CO

Photo # 4653 Location



Mar 17, 2025 at 12:57:20 PM
CO

Photo # 4654 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage RWF 23-25 Frac

Location ID: 433757



Photo # 4655 Location



Photo # 4656 Battery lacks required signage/not in compliance with CECMC rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage RWF 23-25 Frac

Location ID: 433757



Photo # 4657 Disconnected piping



Photo # 4658 Piping disconnected & blind flanged

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage RWF 23-25 Frac

Location ID: 433757



Photo # 4659 Piping disconnected & blind flanged



Photo # 4660 Piping disconnected & blind flanged