

# Inspection Photos

03/17/2025

**Operator:** CAERUS PICEANCE LLC - 10456

**Location ID:** 335676

**Inspection Doc:** 718100310

Garfield County, CO

Aaron Trujillo  
Western Reclamation Work Lead  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335676



**Photo 1:** Photos 1-2 taken from the southwest end of the working pad surface. Photos provide an overview of the Location from northwest, north, northeast to southeast.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335676



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335676



**Photo 3:** Photos taken from the pipeline equipment on the southeast end of the Location. Photo shows containment measure has filled with fluid, and a chemical sheen is apparent. Photo also shows wildlife protection measures are missing or insufficient.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335676



**Photo 4:** Photos taken from the produced water tank on the east end of the Location. Photo shows tank hatch is broken; Operator appears to have taken the top portion of the hatch and placed it upside down over the opening. Tank is improperly closed to prevent emissions from venting.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335676



**Photo 5:** Photos 5-6 taken from the “TA” wells within the southern portion of the pad. Work appears to be in process at the wells.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335676



**Photo 6:** See comments under photo 5.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335676



**Photo 7:** Photo taken from the northeast end of the working pad surface, facing southeast. Photo shows soil stockpile has been placed within areas of the perimeter stormwater diversion ditch- placement of stockpiles within a stormwater diversion ditch does not comport with stockpile protection requirements, and places the soils at risk to commingling with stormwater runoff, and sediment transport.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335676



**Photo 8:** Continued from photo 7. Photo shows erosion log placed at the soil stockpile has been crushed, and is no longer in proper functioning condition to minimize sediment migration for the stockpile. Photo also shows soil stockpile has been placed within areas of the perimeter stormwater diversion ditch.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335676



**Photo 9:** Photos taken from the interim areas on the east end of the Location. Photos examples showing areas where desirable perennial vegetative establishment does not appear to be uniform.