

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/14/2025

Submitted Date:

03/19/2025

Document Number:

717900151**FIELD INSPECTION FORM**Loc ID 306401 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		nikki.graber@state.co.us	
,		cogcc@kpk.com	All Inspections
		laurel.anderson@state.co.us	
,		rwatzman@kpk.com	All Inspections

General Comment:

This is an environmental inspection for Location ID 306401 Camensich Battery 2. Operator to note that this Location ID is associated with the nearby wellheads to the West. This battery shares a location with the Gray 1/Hepp Battery, Location ID 475860. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment: Unused equipment and trash/debris observed at the location.

Corrective Action: Comply with rule 606

Date: 04/04/2025

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment: No spills observed.

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:						
Corrective Action:						Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Inspector noticed all earthen berms were degraded/inadequate. Need to be built up and compacted.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1).				Date: 04/02/2025

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: No spills or releases observed during inspection.

Corrective Action: _____

Date: _____

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

ECMC Comments

Comment

User

Date

This environmental inspection was in with regard to an old complaint from an anonymous complainant. Open thief hatches and stained soil were mentioned in the complaint. Neither of these were observed during the inspection. Complaint/Form 18 Doc# 403361643. The complaint also referenced the Gray1/Hepp Battery which shares a location with the Camenisch Battery 2 and was inspected on the same date. Stained soil and other infractions were observed at the Gray 1/Hepp Battery.

robinsotl

03/19/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717900152	photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6966124