

Inspection Photos
Location Name: Werning 1-2B
API #123-26399



Wellhead and sign



Wellhead

Inspection Photos
Location Name: Werning 1-2B
API #123-26399



Flowline OOSLAT tag