

Inspection Photos

March 18th, 2025

Operator: Hilcorp Energy Company - 10133

Location ID: 325510

Inspection Document #: 714001977

La Plata County, CO

Township: NENW 4 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Davis Gas Unit 1
Location ID: 325510



Photo 1. View of well pad taken from the access point facing center.

Inspection Photos
Location Name: Davis Gas Unit 1
Location ID: 325510



Photo 2. No active erosion and adequate stormwater BMPs observed at the access point and in the eastern interim reclamation areas.

Inspection Photos
Location Name: Davis Gas Unit 1
Location ID: 325510

3/18/25
116° SE



Photo 3. Unused equipment at separator equipment has been removed from location.

Inspection Photos
Location Name: Davis Gas Unit 1
Location ID: 325510



Photo 4. Hole/erosion tunnel forming along the eastern perimeter berm.