

# Inspection Photos

03/17/2025

**Operator:** CAERUS PICEANCE LLC - 10456

**Location ID:** 487650

**Inspection Doc:** 718100314

Rio Blanco County, CO

Aaron Trujillo  
Western Reclamation Work Lead  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 487650



**Photo 1:** Photos taken from the access road intersection, east of the Location. Photos show only sign associated with the Location. Photo also shows empty tube that appears to have been intended for the Form 2A permit and associated Form 4s. Permit/Form 4s have not been posted on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 487650



**Photo 2:** Continued from photo 1. Photo shows sign.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 487650



March 17, 2025

**Photo 3:** Photo taken from the access road, east of the Location, facing west. Road appears to have been stabilized with use of gravel / road base material.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 487650



**Photo 4:** Photos taken from the southeast end of the Location, facing west and north. Photo left shows the Secondary Road leading along the west end of the Location; photo right shows the Primary Road leading to the location entrance on the south end of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 487650



**Photo 5:** Photos taken 5-6 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 487650



**Photo 6:** See comments under photo 5.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 487650



**Photo 7:** Photos taken from the south end of the Location; photo left facing west. Photos show topsoil stockpile stored on the south and west ends of the Location. Hydromulch has been sprayed on the soils, and erosion logs have been installed along the toe/perimeter of the stockpile.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 487650



**Photo 8:** Photos left taken from the “Secondary Access Point on the west end of the Location, facing west; photo right taken from the “Primary Access Point” on the south end of the Location, facing south. Photos show that either a “Tracking Control Pad”, or a “Rumble Strip” VTC, has not been installed at either access point in accordance with good engineering practice. Operator appears to have only placed gravel within these areas.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 487650



**Photo 9:** Photos taken from the northwest end of the Location, facing northwest and north. Photo shows stormwater basin on the western perimeter of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 487650



**Photo 10:** Photos 10-11 taken from the north end of the Location, facing west, northeast, northeast and east. Photo shows perimeter controls including berm at the toe of the fill slopes, stormwater basins on the west and north end of the Location, and a berm along the perimeter of the Location's disturbance.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 487650



**Photo 11:** See comments under photo 10.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 487650



**Photo 12:** Photos taken from the north end of the Location, facing north and northeast. Photo shows stormwater basin.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 487650



**Photo 13:** Photos taken from the east end of the Location, facing east and southeast. Photo shows stormwater basin, and berms at the toe of the fill slope and perimeter of the Location.