

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/13/2025

Submitted Date:

03/13/2025

Document Number:

714202259

**FIELD INSPECTION FORM**

Loc ID 419400 Inspector Name: Santistevan, Brittani On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10459  
Name of Operator: EXTRACTION OIL & GAS INC  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202

**Findings:**

- 9 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
419395	WELL	SI	04/01/2022	GW	123-32227	MORO FARMS 31-29	SI
419399	WELL	SI	04/01/2022	OW	123-32231	MORO FARMS CNE-29	SI
419406	WELL	SI	04/01/2022	OW	123-32234	MORO FARMS 41-29	SI

**General Comment:**

[This is an audit of MORO FARMS 31-29, CNE-29, 41-29 scout card and related documents followed by a field inspection.](#)

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Signs appear to be damaged. See attached photos.		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 04/14/2025
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Overgrown, dead vegetation and debris inside and outside of location. See attached photos.		
Corrective Action:	Comply with Rule 606.		Date: 03/31/2025
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	6' chain link.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead			# 3
Comment:			
Corrective Action:			Date:
Type: Plunger Lift			# 3
Comment:			
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 419395 Type: WELL API Number: 123-32227 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI; Form 6A in well file.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 03/27/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 419399 Type: WELL API Number: 123-32231 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI; Form 6A in well file.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 03/27/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 419406 Type: WELL API Number: 123-32234 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI; Form 6A in well file.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 03/27/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      WEATHER CONDITIONS: sunny, dry ground                      On Thursday, March 13, 2025 at approximately 1230, I, Inspector Brittani Santistevan, conducted an on-site inspection at MORO FARMS 41-29, CNE-29, 31-29 (Extraction Oil &amp; Gas Inc), at location ID: 419400 in WELD COUNTY, Colorado.                      While there, I observed shut-in wellheads.                      During this inspection the following possible compliance issues were observed:                      1. It appears wellhead signs are damaged and do not display operator name and/or emergency #. Install sign to comply with Rule 605.d. (Corrective Action Date: April 14, 2025) See attached photo #5.                      2. It appears to be dead, overgrown vegetation and debris inside and outside of wellhead fencing. Remove to comply with Rule 606. (Corrective Action Date: March 31, 2025) See attached photo #2-4, 6, 7, 9-11.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	santistb	03/13/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404127008	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6958406">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6958406</a>
714202260	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6958404">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6958404</a>