

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/13/2025

Submitted Date:

03/13/2025

Document Number:

714202261**FIELD INSPECTION FORM**Loc ID 419648 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
425995	TANK BATTERY	AC	10/04/2010		-	MORO FARMS NE/4 SEC 29 TANK BATTERY 31-29, CNE-29	AC

**General Comment:**

This is an audit of MORO FARMS NE/4 SEC 29 TANK BATTERY 31-29, CNE-29 scout card and related documents followed by a field inspection.

**Location**Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	It appears the tank battery signage is no longer legible. see attached photos.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	04/14/2025
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	It appears to be dead vegetation and debris on various areas of location. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	03/31/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	6' chain link.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	6' chain link.		
Corrective Action:		Date:	

**Equipment:**

Type: Bird Protectors	# 5		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	DCP Midstream		
Corrective Action:		Date:	

Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with other tanks.				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	425995	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	AC

Idle Well

Purpose:

☒ Shut In

☐ Temporarily Abandoned

Reminder:

EQUIPMENT ONSITE

Comment:

SI; facility appears to be shut-in (no pilot on)

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test:

Annual Brhd Completed?

Last Brhd Test Results

Initial Surf Csg Pressure:

Fluid Type:

End Surf Csg Pressure:

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>WEATHER CONDITIONS: sunny, dry ground</p> <p>On Thursday, March 13, 2025 at approximately 1245, I, Inspector Brittani Santistevan, conducted an on-site inspection at MORO FARMS NE/4 SEC 29 TANK BATTERY31-29, CNE-29 (Extraction Oil &amp; Gas Inc), at location ID: 419648 in WELD COUNTY, Colorado.</p> <p>While there, I observed a shut-in facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. It appears the tank battery signs are no longer legible. Install sign to comply with Rule 605.e. (Corrective Action Date: April 14, 2025) See attached photos #1-3.</p> <p>2. It appears to be dead vegetation and debris on various areas of location. Remove to comply with Rule 606. (Corrective Action Date: March 31, 2025) See attached photos #4-9.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	03/13/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404127009	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6958411">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6958411</a>
714202262	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6958405">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6958405</a>