

Inspection/Audit Photos
Location Name: TEP Rocky Mountain LLC CSF T Pad
Location # 335052



Mar 20, 2025 at 11:53:21 AM
CO



Mar 20, 2025 at 11:52:45 AM
CO

Photo # 5655 From entrance to location

Photo # 5656 Location

Inspection/Audit Photos
Location Name: TEP Rocky Mountain LLC CSF T Pad
Location # 335052



Mar 20, 2025 at 12:23:27 PM
CO



Mar 20, 2025 at 12:26:47 PM

Photo # 5657 Location

Photo # 5658 Location

Inspection/Audit Photos
Location Name: TEP Rocky Mountain LLC CSF T Pad
Location # 335052



Photo # 5659 Location



Photo # 5660 Location

Inspection/Audit Photos
Location Name: TEP Rocky Mountain LLC CSF T Pad
Location # 335052



Photo # 5661 Location



Photo # 5662 Location

Inspection/Audit Photos
Location Name: TEP Rocky Mountain LLC CSF T Pad
Location # 335052



Photo # 5663 Location

Photo # 5664 Location

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC CSF T Pad

Location # 335052



Mar 20, 2025 at 12:14:55 PM
CO



Mar 20, 2025 at 12:15:02 PM
CO

**Photo # 5665 Mechanical Condition - Possible leak on CSF
42B-07-07-91 wellhead casing valve**

**Photo # 5666 Mechanical Condition - Possible leak on CSF
42B-07-07-91 wellhead casing valve**

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC CSF T Pad

Location # 335052



Photo # 5667 Mechanical Condition - Possible leak on CSF
42B-07-07-91 wellhead casing valve



Photo # 5668 Mechanical Condition - Possible leak on CSF
42B-07-07-91 wellhead casing valve

Inspection/Audit Photos
Location Name: TEP Rocky Mountain LLC CSF T Pad
Location # 335052



Photo # 5669 Wildlife egress board improperly placed/cellar cover has rendered egress board unusable

Photo # 5670 Egress board adjusted by TEP lease operator during inspection