

Inspection/Audit Photos

Location Name: QB Energy SAVAGE 2-31 (RL2) Pad

Location #: 324005



Photo # 4754 From entrance to location




Photo # 4755 Location



Inspection/Audit Photos
Location Name: QB Energy SAVAGE 2-31 (RL2) Pad
Location #: 324005



Photo # 4756 Location



Photo # 4757 Location

Inspection/Audit Photos
Location Name: QB Energy SAVAGE 2-31 (RL2) Pad
Location #: 324005



Photo # 4758 Location




Photo # 4759 Location

Inspection/Audit Photos
Location Name: QB Energy SAVAGE 2-31 (RL2) Pad
Location #: 324005



**Photo # 4760 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife**



**Photo # 4761 Barbed wire fence needs maintenance/wildlife
hazard**

Inspection/Audit Photos
Location Name: QB Energy SAVAGE 2-31 (RL2) Pad
Location #: 324005



Photo # 4762 Barbed wire fence needs maintenance/wildlife hazard



Photo # 4763 Barbed wire fence needs maintenance/wildlife hazard

Inspection/Audit Photos
Location Name: QB Energy SAVAGE 2-31 (RL2) Pad
Location #: 324005



Mar 17, 2025 at 2:35:15 PM

Photo # 4764 Barbed wire fence needs maintenance/wildlife hazard



Mar 17, 2025 at 2:35:33 PM

Photo # 4765 Barbed wire fence needs maintenance/wildlife hazard

Inspection/Audit Photos
Location Name: QB Energy SAVAGE 2-31 (RL2) Pad
Location #: 324005



Mar 17, 2025 at 2:35:35 PM

Photo # 4766 Barbed wire fence needs maintenance/wildlife hazard



Mar 17, 2025 at 2:35:44 PM

Photo # 4767 Barbed wire fence needs maintenance/wildlife hazard

Inspection/Audit Photos
Location Name: QB Energy SAVAGE 2-31 (RL2) Pad
Location #: 324005



Photo # 4768 Barbed wire fence needs maintenance/wildlife hazard



Photo # 4769 Barbed wire fence needs maintenance/wildlife hazard