

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/17/2025

Submitted Date:

03/21/2025

Document Number:

698603335**FIELD INSPECTION FORM**Loc ID 303802 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253619	WELL	PR	02/18/1994	GW	125-07497	WHITE STAR FARMS 4-23	PR

General Comment:

Inspector completed Follow-up inspection 03/17/2025 as required by FIR to ensure corrective actions taken by Operator adequately address and comply with rule requirements cited in 01/23/25 FIR document number 698603122. All corrective actions identified in FIR have been completed.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Corrective Action cited in 01/23/25 FIR document number 698603122. Produced water leaking from wellhead packing. Spill less than 1 bbl.

Corrective actions completed per Rule 912.b.

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment

1

Comment:

Wellhead. Casing production. Rods and tubing in the wellbore. Tubing valve open.

Casing valve open.

Corrective Action cited in 01/23/25 FIR document number 698603122. Well was found to be leaking at packing at time of inspection.

Corrective actions completed per Rule 603.c.(14).

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

