

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/17/2025

Submitted Date:

03/21/2025

Document Number:

698603336

FIELD INSPECTION FORM

Loc ID 426947 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10699
 Name of Operator: OWN RESOURCES OPERATING LLC
 Address: 305 S RIDGE STREET #6279
 City: BRECKENRIDGE State: CO Zip: 80424

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426903	WELL	PR	02/10/2012	GW	125-12062	Lazy Day 4-24	PR

General Comment:

Inspector completed Follow-up inspection 03/17/2025 as required by FIR to ensure corrective actions taken by Operator adequately address and comply with rule requirements cited in 01/14/25 FIR document number 698603025. Corrective actions have not been performed to identify well associated with separation equipment.

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Separator at shared location has no signage to determine well association. Current signage at location indicates unmarked separator may belong to Bryce Day 3-24 or Lazy Day 4-24. Based on signage and equipment on location Inspector is unable to determine well assignment.		
Corrective Action:	Install sign to comply with Rule 605.e. Assigned corrective action dates remains the same to document period of non-compliance.	Date:	02/20/2025

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No _____

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 426903 Type: WELL API Number: 125-12062 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698603366	Inspection photos.	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6970138