


Inspection Photos
Location Name: Eyestone 3-35
API Number: 125-07469



1. Lease sign at well location as seen 02/06/2025.



2. Lease sign at well location as seen 03/17/2025.

Inspection Photos
Location Name: Eyestone 3-35
API Number: 125-07469



3. View of wellhead as seen 02/06/2025.



4. View of wellhead area as seen 03/17/2025. Note saturated soil around wellhead.

Inspection Photos
Location Name: Eyestone 3-35
API Number: 125-07469



**5. View of broken power panel post and panel as seen
02/06/2025.**



**6. View of broken power panel post and panel as seen
03/17/2025.**

Inspection Photos
Location Name: Eyestone 3-35
API Number: 125-07469



7. View of check valve with missing cap as seen 02/06/2025.



**8. View of check valve with missing cap as seen 03/17/2025.
Note check valve cap on ground at edge of rust stain.**

Inspection Photos
Location Name: Eyestone 3-35
API Number: 125-07469



9. View of leaking check valve as spill release point as seen 02/06/2025.



10. View of area below leaking check valve as spill release point. Note check valve cap on ground.

Inspection Photos
Location Name: Eyestone 3-35
API Number: 125-07469



11. View of roof damage on meter shed as seen 02/06/2025.



12. View of roof damage on meter shed as seen 03/17/2025.