

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/17/2025

Submitted Date:

03/22/2025

Document Number:

698603340**FIELD INSPECTION FORM**Loc ID 303782 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253591	WELL	PR	02/18/1994	GW	125-07469	EYESTONE 3-35	PR

General Comment:

Inspector completed Follow-up inspection 03/17/2025 as required by FIR to ensure corrective actions taken by Operator adequately address and comply with rule requirements cited in 02/06/25 FIR document number 698603170. Corrective Actions have not been performed or are insufficient to prevent recurrence. Assigned corrective action dates remains the same to document period of non-compliance.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐

Spills:					
Type	Area	Volume			
Produced Water	WELLHEAD				
Comment:	As cited in 02/06/25 FIR document number 698603170. Unable to determine volume. Soil staining would generally indicate the leak has been ongoing and not repaired or identified.				
Corrective Action:	Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 912.b.			Date:	02/12/2025
	Assigned corrective action dates remains the same to document period of non-compliance.				

In Containment: No

Comment:

Water line on wellhead was found to be leaking at the check valve at time of inspection. Check valve cap had been removed and not replaced effectively removing back pressure and fluid containment within the line.

Reported to Field Forman 2/6/25 at 3:30 PM.

Continued release was reported to Field Forman 03/17/2025 2:11 PM.

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	As cited in 02/06/25 FIR document number 698603170. Pump Jack Power and Control Panel. Mounting post has rotted and broken off at grade. Panel is partially detached from post and resting on well fencing.		
Corrective Action:	Comply with Rule 609.a.		Date: 02/25/2025
	Assigned corrective action dates remains the same to document period of non-compliance.		
Type: Ancillary equipment	# 1		
Comment:	As cited in 02/06/25 FIR document number 698603170. Wellhead. Casing production. Rods and tubing in the wellbore. Tubing valve closed. **Open ended valve on the line**. Casing valve open. Water line leaking produced water at the check valve.		
	Reported to Field Forman 2/6/25 @ 3:30 pm.		
	Continued release was reported to Field Forman 03/17/2025 2:11 PM.		
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).		Date: 02/07/2025
	Assigned corrective action dates remains the same to document period of non-compliance.		
Type: Other	# 1		
Comment:	As cited in 02/06/25 FIR document number 698603170. Shared Remote Gas Meter Shed. Roof is damaged with large section of roof panel broken out.		
Corrective Action:	Comply with Rule 609.a.		Date: 02/25/2025
	Assigned corrective action dates remains the same to document period of non-compliance.		
Type: Gas Meter Run	# 1		

Comment:	As cited in 02/06/25 FIR document number 698603170. Remote Gas Meter Run located on CR N & Access at shared gathering location. Gas Meter Run. Chart in Meter Box dated 2-3-25. Meter Calibration/Test Log dated 2-5-24. Well Inlet Valve open. Gas Outlet Valve open. **Meter is due calibration**.		
Corrective Action:	Corrective Action identified in FIR has been completed.	Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	253591	Type:	WELL	API Number:	125-07469	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Rods and tubing in wellbore. Tubing valve closed. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open. Electronic Well File reflects last Production/Status reported 1/1/2025 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.								
Corrective Action:								Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698603370	Inspection photos.	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6970376