

Inspection/Audit Photos

Location Name: TEP Rocky Mountain CSF 33B-07-07-91 Pad

Location # 335051



Photo # 6178 From entrance to location



Photo # 6179 Location

Inspection/Audit Photos

Location Name: TEP Rocky Mountain CSF 33B-07-07-91 Pad

Location # 335051



Photo # 6180 Location



Photo # 6181 Location

Inspection/Audit Photos

Location Name: TEP Rocky Mountain CSF 33B-07-07-91 Pad

Location # 335051



Photo # 6182 PRV vent line on separator does not comply with CECMC pressure safety device rules



Photo # 6183 PRV vent line on separator does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP Rocky Mountain CSF 33B-07-07-91 Pad

Location # 335051



Photo # 6184 Bird protection on separator insufficient
/burner stack available for entry by wildlife/wildlife hazard



Photo # 6185 Wellhead sign lacks required information