

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/20/2025

Submitted Date:

03/22/2025

Document Number:

708906074

**FIELD INSPECTION FORM**Loc ID 335051 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

18 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284681	WELL	SI	05/01/2024	GW	045-12254	CSF 33B-07-07-91	SI

**General Comment:****CECMC Inspection/Audit Report Summary**

On 03/20/2025 at approximately 14:38 hours, I, Compliance Specialist, Wayne Smelser  
Conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC CSF 33B-07-07-91 Pad.  
Location # 335051 in Garfield County Colorado.  
Location is within Black Bear Habitat area.  
While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

1. Signs/Marker - Wellhead sign lacks required information with a CA date of 04/21/2025
2. Equipment - Bird protection on separator unit insufficient/wildlife hazard with a CA date of 03/29/2025
3. Equipment - PRV vent line on separator does not comply with CECMC pressure safety device rules with a CA date of 03/29/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection/audit report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellhead sign lacks required information		
Corrective Action:	<p>A permanent sign will be conspicuously located at the wellhead and will identify:</p> <p>A. The Well name;</p> <p>B. The API number; and</p> <p>C. Its legal location, including the quarter/quarter section.</p> <p>When no associated Tank battery is present at the Oil and Gas Location, the following additional information is required on the Well sign:</p> <p>A. Name of the Operator;</p> <p>B. Telephone number at which the Operator can be reached at all times;</p> <p>C. Telephone number for local emergency services (911 where available); and</p> <p>D. The public road used to access the Well.</p>	Date:	04/21/2025

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Small amount of staining on location		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Bird protection on separator insufficient/burner stack available for entry by wildlife/wildlife hazard		
Corrective Action:	Comply with multiple series 600 rules	Date:	03/29/2025
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:	Well not on plunger lift		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	PRV vent line on separator does not comply with CECMC pressure safety device rules		
Corrective Action:	Comply with CECMC pressure safety device rules	Date:	03/29/2025
Type: Bradenhead	# 1		
Comment:	Taylor plug located on bradenhead, bradenhead valve is accessible.		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	284681	Type:	WELL	API Number:	045-12254	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____									
Comment: <div>Shut In Last produced April 2024</div>									
Corrective Action: _____ Date: _____									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Gravel				Sparse to none
		Culverts				
Gravel						Sparse to none in some areas
Compaction						Small amount of light compaction
		Compaction				Light compaction in some sections

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<a href="#">Please refer to Signs/Marker &amp; Equipment for corrective actions</a>	smelserw	03/22/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708906075	Inspection/Audit 708906074 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6970480">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6970480</a>
708906076	Inspection/Audit 708906074 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6970481">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6970481</a>