

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain CSF 14C-09-07-91 Pad

Location # 324241



Mar 20, 2025 at 3:38:39 PM  
CO



Mar 20, 2025 at 3:42:12 PM  
CO

Photo # 6362 From entrance to location

Photo # 6363 Location

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain CSF 14C-09-07-91 Pad

Location # 324241



Photo # 6364 Location



Photo # 6365 Location



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain CSF 14C-09-07-91 Pad

Location # 324241



Photo # 6366 Location



Photo # 6367 Location

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain CSF 14C-09-07-91 Pad

Location # 324241



**Photo # 6368 PRV vent line on separator does not comply with CECMC pressure safety device rules**



**Photo # 6369 PRV vent line on separator does not comply with CECMC pressure safety device rules**



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain CSF 14C-09-07-91 Pad

Location # 324241



Photo # 6370 Wellhead sign lacks required information