

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/14/2025

Submitted Date:

03/16/2025

Document Number:

708906005

FIELD INSPECTION FORM

Loc ID: 324057 Inspector Name: Smelser, Wayne On-Site Inspection: 2A Doc Num: 400505143

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 19 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211599	WELL	PR	06/27/1999	GW	045-07360	CLOUGH RMV 205-20	PR

General Comment:

[CECMC Inspection/Audit Report Summary](#)
On 03/14/2025 at approximately 12:45 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC CLOUGH RMV 205-20 pad. Location # 324057 in Garfield County Colorado. Location is within High Priority/Density Habitat areas. Location is approximately 34 yards from a creek/drainage that contributes to the Colorado River. While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

- 1. Housekeeping - Stored tank on location with a CA date of 04/15/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection/audit report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Stored tank on location Additionally there are multiple unsecured flanges & other openings on the tank that are available for entry by wildlife/wildlife hazards		
Corrective Action:	Comply with multiple 600 series rules		Date: 04/15/2025

Overall Good:

Spills:			
Type	Area	Volume	
In Containment:	No		
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:

Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	Injection well		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Taylor plug located on bradenhead, bradenhead valve is accessible.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Cataflow Equipment not listed in operators FORM 2A or FORM 4 SUNDRY/not in compliance with CECMC rules		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		

Comment:		Centralized containment				Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	1	<100 BBLS	STEEL AST		,		
Comment:		Tank equipped with telemetry				Date:	
Corrective Action:						Date:	
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)	80 bbl						
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent					
Comment:		Centralized containment				Date:	
Corrective Action:						Date:	
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:							
Flaring:							
Type							
Comment:							
Corrective Action:							

Inspected Facilities

Facility ID: 211599 Type: WELL API Number: 045-07360 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse to none in some areas
		Ditches				
		Culverts				
Compaction						Light compaction in some areas
Berms						
		Compaction				
		Gravel				Sparse

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Housekeeping for corrective action	smelserw	03/16/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404129262	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6961463
708906006	Inspection/Audit 708906005 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6961461
708906007	Inspection/Audit 708906005 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6961462