

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/23/2025

Submitted Date:

03/23/2025

Document Number:

716201626

FIELD INSPECTION FORM

Loc ID: 332754
Inspector Name: Carlile, Craig
On-Site Inspection:
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271456	WELL	PR	11/01/2024	GW	123-22060	ARISTOCRAT ANGUS 3-6-4	PR
271457	WELL	PR	11/01/2024	OW	123-22061	ARISTOCRAT ANGUS 1-6-4	PR
424349	WELL	PR	11/01/2024	GW	123-33996	ARISTOCRAT ANGUS 4-8-4	PR

General Comment:

Alternative method of inspection.
Previous corrective action inspection document number: 716201622
FIRR Response Document number: 404131404 included photo providing evidence of compliance with previous corrective action inspection.
Photos attached.

Inspected Facilities

Facility ID: 271456 Type: WELL API Number: 123-22060 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 271457 Type: WELL API Number: 123-22061 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 424349 Type: WELL API Number: 123-33996 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716201627	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6970862