

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/23/2025

Submitted Date:

03/23/2025

Document Number:

716201628

FIELD INSPECTION FORM

Loc ID 332754 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245865	WELL	PA	03/05/2024	GW	123-13660	ARISTOCRAT ANGUS 24-4	PA
271453	WELL	PA	02/02/2023	GW	123-22057	ARISTOCRAT ANGUS 2-7-4	PA
271454	WELL	PA	02/02/2023	OW	123-22058	ARISTOCRAT ANGUS 2-5-4	PA
271455	WELL	PA	02/02/2023	GW	123-22059	ARISTOCRAT ANGUS 2-	PA
424342	WELL	PA	03/05/2024	GW	123-33993	ARISTOCRAT ANGUS 4-6-4	PA
424344	WELL	PA	07/07/2023	GW	123-33994	ARISTOCRAT ANGUS 4-4	PA

General Comment:

Wells have been plugged with active wells remaining on location as can be seen in ECMC document number: 716201623

Inspected Facilities

Facility ID: 245865 Type: WELL API Number: 123-13660 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 271453 Type: WELL API Number: 123-22057 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 271454 Type: WELL API Number: 123-22058 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 271455 Type: WELL API Number: 123-22059 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 424342 Type: WELL API Number: 123-33993 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 424344 Type: WELL API Number: 123-33994 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12