

Inspection Photos  
Location: SE Campo Unit 1101W  
Location ID: 321111  
API # 05-009-06489



Photo 1 –Well placard

Photo 2 – Wellhead and electrical equipment

Inspection Photos  
Location: SE Campo Unit 1101W  
Location ID: 321111  
API # 05-009-06489



Photo 3 – Location

Photo 4 – Wellhead, OOSLAT Applied

Inspection Photos  
Location: SE Campo Unit 1101W  
Location ID: 321111  
API # 05-009-06489



Photo 5 – Wellhead and OOSLAT