

Inspection Photos
Location: SE Campo Unit 602
Location ID: 321110
API # 05-009-06483



Photo 1 –Well placard

Photo 2 – Historic wellhead and electrical equipment

Inspection Photos
Location: SE Campo Unit 602
Location ID: 321110
API # 05-009-06483



Photo 3 – Wellhead excavation Rem Project # 37141, Fencing not adequate

Photo 4 – Wellhead excavation Rem Project # 37141

Inspection Photos
Location: SE Campo Unit 602
Location ID: 321110
API # 05-009-06483



Mar 20, 2025 at 1:48:02 PM
+37.028341, -102.555326
ECMC



Mar 20, 2025 at 1:48:14 PM
+37.028307, -102.555218
ECMC

Photo 5 – Spoil Pile on liner, no berm, materials are migrating due to stormwater impacts

Photo 6 – Spoil Pile on liner, no berm, materials are migrating due to stormwater impacts

Inspection Photos
Location: SE Campo Unit 602
Location ID: 321110
API # 05-009-06483




Photo 7 – Ancillary equipment, unused equipment

Photo 8 – Ancillary equipment, unused equipment

Inspection Photos
Location: SE Campo Unit 602
Location ID: 321110
API # 05-009-06483



Photo 9 – Cement fines on ground east of wellhead

Photo 10 – Cement fines on ground

Inspection Photos
Location: SE Campo Unit 602
Location ID: 321110
API # 05-009-06483



Photo 11 – Flowline at wellhead